



15.2 FL OZ. SEALANT REFILL
10179

EMERGENCY TIRE SEALANT REFILL BOTTLE

- SEALS INSTANTLY
- TIRE SENSOR SAFE
- NO NEED TO REMOVE THE VALVE CORE



SEALANT REFILL FOR
FLAT TIRE REPAIR KITS
50122 AND #50123



CAR / TRAILER



AVAILABLE NOW

15.2 FL OZ Flat Tire Repair Kit Refill

PART# 10179 REV082720ART* / REV F**

	EA.	DIMENSIONS	UPC/CASE CODE
UNIT	1	8.500" H x 2.500" W x 3.750" D • 1.524 LBS	716281509209
INNER	4	9.250" H x 5.563" W x 8.063" L • 6.376 LBS	10716281509206

U.S. Patent # 7,868,061



ITW Global Tire Repair • 125 Venture Drive, Suite 210, San Luis Obispo, CA 93401 • PHONE: 805.489.0490 • FAX: 805.489.1920
ITW Global Tire Repair, GmbH • Carl-Benz Str. 10, 88696, Owingen, Germany • PHONE: +49-7551-9200-0 • FAX: +49-7551-9200-990

WWW.SLIME.COM



15.2 FL OZ. SEALANT REFILL SPEC SHEET 10179

CONTAINS:

- 15.2 fl. oz. Flat Tire Repair Kit Sealant 8.75in. x 2.5in. x 3.75in. (222.3mm x 63.5mm x 95.3mm)



SEALANT/
AIR HOSE

LINKS

[PRODUCT WEB PAGE](#)

[SDS SHEET](#)

[HI RES IN & OUT OF PACKAGE SHOTS,
6-SIDED PHOTOS, INSTRUCTIONS & UPC](#)

[VIDEO \(N/A\)](#)

[PRODUCT WARRANTY](#)

PART # 10179



ADDITIONAL SET UP INFO

HTS CODE: 3506.10.5000

COUNTRY OF ORIGIN: CHINA


PALLET INFORMATION:

CASES PER LAYER (TIE): 39

LAYERS PER LOAD (HIGH): 4

INNER CASES PER PALLET: 156

EACHES PER PALLET: 624



***ART REVISION CHANGES:**

REV010220• Updated label to match 50122 package.

REV0827220• Updated formula to V1D formula and warnings to be compliant.

****REVISION CHANGES:**

REV A • Initial Release.

REV B • Updated existing hose connector to new connector.

REV C • Updated artwork for CTL compliance, changed bottle color from white to PMS 368 green.

REV D • Added distance verbiage warning to label.

REV E • Updated art to be consistent with existing spair line. Sealant part number updated.

REV F • Updated formula to V1D formula and updated warnings to be compliant.

ITW Global Tire Repair • 125 Venture Drive, Suite 210, San Luis Obispo, CA 93401 • PHONE: 805.489.0490 • FAX: 805.489.1920

ITW Global Tire Repair, GmbH • Carl-Benz Str. 10, 88696, Owingen, Germany • PHONE: +49-7551-9200-0 • FAX: +49-7551-9200-990